

Soldiers & Sailors Monument Reconstruction

Project M071-323M

Located at Riverside Drive & W89th Street in the Borough of Manhattan

Landmarks Preservation Commission Review June 11, 2024

WXY architecture + urban design NYC Parks

Total Budget: \$62.3M (Mayoral) FY 2023

Project Size: 25,000SF

Project Goals

- The complete restoration of the Soldiers & Sailors Monument, its surrounding terraces, and all associated structures.
- ADA compliant accessibility to all exterior levels of the monument.*
- Lighting that is safe, secure, easy to maintain, and elevates the appearance of the monument's facade at night.

*The monument's interior will remain inaccessible to all public.








Soldiers & Sailors Monument Reconstruction Riverside Park | **Project Goals**



Borough: Manhattan



Neighborhood: Upper West Side | CB7



Site: Riverside Park



 $W \times Y$ Cbb LERA $\frac{1923}{2003}$ 100



Soldiers & Sailors Monument Reconstruction Riverside Park | Project Location

NYC Parks





1— Approaching the Monument from the South along Riverside Drive, c. 1935





Soldiers & Sailors Monument Reconstruction Riverside Park | Historical Views





Photo Key





1—Aerial view from west, c. 1934



NYC Parks



Soldiers & Sailors Monument Reconstruction Riverside Park | Historical Views




Photo Key





1— View from he South Plaza, 1911



2— View from South Plaza, 2024


Photo Key






Soldiers & Sailors Monument Reconstruction Riverside Park | Site Photos: Historic & Existing

NYC Parks












Soldiers & Sailors Monument Reconstruction Riverside Park | Monument History
















1902 The Monument is opened shortly before the Upper & Lower Terraces are completed.



1902 The Upper & Lower Terraces are completed.





1962 Last major restoration campaign—the terraces are repaved with Crab Orchard sandstone, balustrades are replaced, cannon balls are relocated, the side is regraded, and the flagpole is replaced.










Soldiers & Sailors Monument Reconstruction Riverside Park | Monument Evolution







1902 Terraces are completed in herringbone brick pavers.



1962 Last major restoration campaign—the terraces are repaved with Crab Orchard sandstone.

Soldiers & Sailors Monument Reconstruction Riverside Park | Terrace Materials







Bronze Bronze is featured at the flag post, the tablets, the door itself and the interior cover to the vault. On the drum, Bronze is also used as a screen detail.




Crab Orchard Sandstone

Originally, the plazas featured a pattern of white marble banding with a brick field. In 1935 the brick was replaced by concrete.



During the 1962 restoration campaign, extensive work was conducted on the plazas. Additionally, the deteriorated original brick paving, most of which had already been replaced with concrete (as shown in period photographs), was replaced with the brownish-colored Crab Orchard sandstone.









Soldiers & Sailors Monument Reconstruction Riverside Park | Monument Materials The marble used for the monument and plaza balustrade and piers was sourced from Dorset, Vermont

Indiana Limestone

During the 1962 campaign, extensive work was done at the terraces and Belvedere— including the replacement of all of the original marble balustrades, their bases and railings, with Indiana limestone.

Milford Pink Granite

Milford Pink Granite was only used on the north approach stair.

Granite

The granite for the base and steps is reportedly quarried from the Lacasse Quarry located at Derby, Orleans County, Vermont.











(2) The existing marble, c. 1902, is to be restored.

1

The existing crab orchard sandstone, c. 1962, is (3) proposed to be replaced with custom brick pavers as per the original Stoughton & Stoughton design intent



The existing limestone balustrade, (4) c. 1962, is to be restored




NYC Parks





Soldiers & Sailors Monument Reconstruction Riverside Park | **Restoration Palette**

The existing grey granite, c. 1902, is to be restored.



WX**Y** <u>cbb</u> <u>LERA</u> <u>100</u>

1— Deteriorated Crab Orchard paving



2— Evidence of water intrusion & damage

ELY T


...







3— Deterioration of masonry elements



Terrace Reconstruction & Repaving

- Rebuild sub-grade assembly
- Install new drainage
- Reset & replace existing materials



Tower Exterior Repair

- Remediate deteriorated mortar & masonry joints
- Repair & replace roofing and flashing
- Repair & restore corroded metal elements



- **Tower Interior Repair**








Soldiers & Sailors Monument Reconstruction Riverside Park | Scope of Restoration

- Remediate deteriorated mortar & masonry joints - Repair and restore mosaic tile floor - Repair & restore corroded metal elements







Soldiers & Sailors Monument Reconstruction Riverside Park | Existing Conditions: Site

NYC Parks


•


- **Project Limit**
- **Monument Access**
- **Tripping Hazard**
- **Existing Trees**
- **Open Lawn Area**
- **Rock Outcropping**
- **Tree pits**
- **Planted Beds**
- **Asphalt Pavement**
- **Hexagonal Paver**
- **Granite Stairs**
- Cobblestone
- **Crab Orchard Pavers**
- Marble Paving Bands
- Bronze Tablets
- **Granite Benches**
- Site Benches
- Cannon

Cannonballs

Lamp Posts

Bus Stops










Soldiers & Sailors Monument Reconstruction Riverside Park | Site Analysis - Slope Analysis

Legend

mm

- **Project Limit**
- **Stormwater Surface Flow**
- **Existing Spot Grade**
- Low Slopes <5%
- Moderate Slopes ≥5%-10%
- Steep Slopes ≥10%-15%
- Severe Slopes ≥15%








Soldiers & Sailors Monument Reconstruction Riverside Park | Site Analysis

- **Project Limit**
- **Typical Site Approaches**
- Site Area with Potential for Programming
- Cannonballs
- Regrading Recommended for Universal Access
- Soil Stabilization Recommended








Soldiers & Sailors Monument Reconstruction Riverside Park | Site Analysis - Surface Conditions

Legend

 ∇

- **Project Limit**
- **Vegetative Screening**
 - Vistas
 - **Stormwater Ponding**
 - **Open Landscape**
 - Major Critical Root Zones to Avoid
 - **Pavement in Poor** Condition
 - **Empty Tree Pits**







Soldiers & Sailors Monument Reconstruction Riverside Park | Monument Plan: Universal Access Impediments


Legend




Inaccessible Areas Uneven Stone Paving


Access Barriers

Monument interior closed to the public









 \bigotimes







Soldiers & Sailors Monument Reconstruction Riverside Park | Tree Inventory


Stump Removal

Park Tree Canopy Information

67.2% Parkland Canopy Cover 3.6% Canopy Change 2010-2017

Note: Canopy Information provided for extents of Riverside Park, localized site data not available.

Heat Vulnerability Index Site is not in a high HVI area








Soldiers & Sailors Monument Reconstruction Riverside Park | **Existing Fence Diagram**

NYC Parks

MEDIUM FENCES FENCES 4' - 7'-6" HT. (x = HEIGHT) x' Steel LOW FENCES FENCES 2'-6" - 3'-6" HT. (x = HEIGHT) x' Steel **TEMPORARY RANGE FENCES** FENCES 4'-0" HT. (x = HEIGHT) ____X'____Steel HANDRAILS **TYPICAL HEIGHT, 2'-10"** STEEL












Soldiers & Sailors Monument Reconstruction Riverside Park | **Proposed Plan - Site**

- **Project Limit**
- **Existing Trees**
- **Rock Outcropping**
- **Planted Beds**
- **Existing Asphalt Pavement**
- **Existing Hexagonal Paver**
- **New Brick Pavers**
- **Existing Marble Paving Bands**
- **Existing Bronze Tablets**
- **Existing Cannon**
- **Existing Cobblestone**
 - **Relocated Cannonballs**
- **New Granite Terrace Extension**
- New Walkways / Ramps
- **New Handrail Locations**
- Handrails to be Replaced for Code Compliance












Soldiers & Sailors Monument Reconstruction Riverside Park | Monument Plan: Terrace Extension


7 N








Soldiers & Sailors Monument Reconstruction Riverside Park | Site Plan: Garden Walkway





Soldiers & Sailors Monument Reconstruction Riverside Park | Garden Walkway: Section A-A'


NYC Parks



WXY Cbb <u>LERA</u> <u>1723</u> 100

Soldiers & Sailors Monument Reconstruction Riverside Park | Garden Walkway: Section B-B'

NYC Parks



1962 Balustrade components to be removed and salvaged for use where needed in monument restoration







Soldiers & Sailors Monument Reconstruction Riverside Park | Garden Walkway: Balustrade Impact at Upper Terrace







Soldiers & Sailors Monument Reconstruction Riverside Park | Garden Walkway: Balustrade Impact at Upper Terrace



1962 Balustrade components to be removed and salvaged for use where needed in monument restoration

7 36 (ST (GR) 04 EA: 1 DISPLACED STONE STE 5 ST (MA) 04 EA: 2 DISPLACED STONE WITH CONCRETE LEVELER MARBLE BORDER, TYP. 34 (ST (MA) 04 | EA: 1 3 (PO 01 WIDE OPEN JOIN -(ST (MA) 05 S EXISTING DUTCHMA INSIDE FACE SE- 1 282 28
 INSIDE
 FACL

 (ST (MA) 03
 [SF: 1]
 281 284


 MISSING
 DUTCHMAN
 NOT
 INCLUDED
 [ST (MA) 05] SF: 1]

 EXISTING
 DUTCHMAN
 NOT
 INCLUDED
 [ST (MA) 05] SF: 1]
286 282 287 288 ST (MA) 03 SF: 3 ST (MA) 03 SF: 2 282 283 MISSING DUTCHMAN ST (MA) 02 SF: 1 287 289 291 FAILING PATCH (ST (LI) 01 LF: ST (MA) 03 SF: 2 287 289 (ST (MA) 03 SF: 1 MISSING CORNER 278 279 ST (MA) 05 SF: 3 EXISTING DUTCHMAN 279 (ST (MA) 05 SF: 2 EXISTING DUTCHMAN INSIDE FACE 280 (ST (MA) 03 SF MISSING DUTCHMAN OUTSIDE FACE ST (MA) 05 SF: 1 287 292 ST (MA) 05 SF: EXISTING DUTCHMAN OUTSIDE FACE ST (MA) 02 SF: 1 287 289 293 294 282 295 296 (ST (LI) 01 | LF: 4 1) LOWER AND UPPER TERRACE - EAST ELEVATION





Soldiers & Sailors Monument Reconstruction Riverside Park | Garden Walkway: Balustrade Impact at Lower Terrace












Soldiers & Sailors Monument Reconstruction Riverside Park | Garden Walkway: Balustrade Impact at Lower Terrace










Soldiers & Sailors Monument Reconstruction Riverside Park | Relocated Cannonballs










Soldiers & Sailors Monument Reconstruction Riverside Park | Monument Aerial - Existing













Soldiers & Sailors Monument Reconstruction Riverside Park | Monument Aerial - Proposed












Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Key Views










Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Existing

NYC Parks











Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Proposed










Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Existing











Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Proposed





NYC Parks





Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Existing









Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Proposed








Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Existing

NYC Parks








NYC Parks



Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Proposed











Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Existing










Soldiers & Sailors Monument Reconstruction Riverside Park | Walkway Experience: Proposed

NYC Parks











Soldiers & Sailors Monument Reconstruction Riverside Park | Restoration Palette



Granite Pathways, edging, curbs, and new steps to compliment existing monument granite



New Handrails, black




New asphalt pavers to match existing



New 'Landmark Grey' concrete for garden walkway & ramp



Granite Extension of middle terrace to match existing terrace step material



Existing Conditions

Proposed Conditions



Soldiers & Sailors Monument Reconstruction Riverside Park | Before & After

Appendix





Soldiers & Sailors Monument Reconstruction Riverside Park





Sweet Pepperbush Clethra alnifolia



Lowbush Blueberry Vaccinium angustifolium



Bayberry Morella pensylvanica



Northern Spicebush Lindera benzoin



English Laurel Prunus laurocerasus 'Otto Luyken'



Witch Alder Fothergilla gardenii



Northern Bayberry Myrica pensylvanica



Red Osier Dogwood Cornus sericea







Soldiers & Sailors Monument Reconstruction Riverside Park | Plant Palette: Small Trees & Shrubs



Compact Inkberry llex glabra 'Compacta'



Little Bluestem Schizachyrium scoparium



Blue Star Aster Aster cordifolius



Palm Sedge Carex muskingummensis



Goldstrum Orange Coneflower Rudbeckia fulgida 'Goldstrum'



Purple Love Grass Eragrostis spectabilis



Walker's Low Catmint Nepata x faassenii 'Walker's Low'



Red Beauty Yarrow Achillea millefolium 'Red Beauty'



Decorative Onions Allium 'Globemaster'







Soldiers & Sailors Monument Reconstruction Riverside Park | Plant Palette: Ornamental Grasses, Perennials, Forbs, & Bulbs

NYC Parks



Blanket Flower Gaillardia spp.



Daffodils variety Narcissus spp.



Before

Upon the site's opening in 1939, the Nancy Brown Peace Carillon on Belle Isle, Detroit, MI was predominantly surrounded by open lawn.



After

In 2021, an ecological 3 acre garden consisting of perennials, grasses, shrubs, and trees was added in front of and around the Nancy Brown Peace Carillon. Plants were selected based on their hardiness, durability, and ever-changing textures and colors for enjoyment in all four seasons.







Soldiers & Sailors Monument Reconstruction Riverside Park | Design Precedent: Nancy Brown Peace Carillon



NYC Parks

Riverside Park | **Design Precedent: Plant Palette within the Park**